



Inspection Report

Report Date 20/10/2008

Company Phase Electrical Services

Address

Thermographer

Customer

Site Address

Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR InfraCAM Wester	
Image Date	2008:10:20 11:51:14	
Image Name	IR_0369 incoming.jpg	
Emissivity	0.78	
Reflected Temperature	24.0 °C	
Object Distance	1.0 m	

Description

The incoming mains supply was tested under load, although during winter months more circuits will be on. Thermal image shows high heat levels through the mains supply.